

"BEST I" Coil-on-Plug COP Insulator

Product Images

- Colour of COP Insulator Coil / Distributor boot: Blue or Black Silicone rubber compound
- Terminal : Stainless steel
- Cable diameter : depend on specification

"BEST I" COP Insulator

TTTT





Overcome problems of OEM COP Insulator

- No corrosion problem of metal spring conductor inside OEM COP Insulator
- No dielectric leaking
- No gradual increase in fuel consumption and loss of vehicle power



TOP SPARK TECHNOLOGY PTE. LTD.

Special Property

- Low electro-resistance
- Exceed OEM performance without suffering from high frequency noise interference (e.g. RFI and EMI)
- •Low replacement cost
- Stronger spark energy and faster electric transmission

Available Supply Services

- 1) COP Insulator specification in accordance with car types and models
- 2) Tailor made in accordance with customer's requirement
- 3) Tailor made in accordance with supplied sample at no additional cost

Reason to use "BEST I" COP Insulator :

- Does not use metal spring conductor
- No corrosion problem of metal spring conductor
- No fatigue cracking of rubber sealing cap

Picture shows problems of OEM COP Insulators :

